


## Creating a broken isometric view



*This Tech Tip looks at how to create a broken view on an isometric view.*

To create a broken view, you need to start by right mouse clicking on the view and selecting the "Broken View" option from the list.

On the command bar, change the option to "Use Break Axis"



Select the "Define Break Axis" button and then select a line on the drawing view that is the axis for the broken view.



Place your start and end points for the part to be broken out and click Finish.

